



CP-50-1-01-B-П-О6-001  
 CP-50-1-01-B-П-О6-002  
 CP-50-1-01-B-П-О6-003  
 CP-50-1-01-B-П-О6-004



| Размеры, мм |      |     |      |     |      |
|-------------|------|-----|------|-----|------|
| a           | b    | d*  | e*   | f*  | g*   |
| 6,1         | 15,8 | 1,7 | 5,5  | 2,4 | 3,8  |
|             | 16,4 | 2,7 | 9,5  | 3,2 | 3,9  |
|             |      |     |      | 3,6 | 4,55 |
| 7,0         | 22,4 | 4,6 | 12,7 | 5,3 | 6,5  |


CP-50-1-01-B-П-Пр-005  
 CP-50-1-01-B-П-Пр-006



\*Размеры для справок


| Размер, мм |
|------------|
| a          |
| 21         |
| 16,2       |

CP-50-1-01-B-П-Пк-007




\*Размеры для справок

CP-50-1-01-B-Y-O6-008



\*Размеры для справок


CP-50-1-01-P-Π-O6-009  
 CP-50-1-01-P-Π-O6-010  
 CP-50-1-01-P-Π-O6-011  
 CP-50-1-01-P-Π-O6-012  
 CP-50-1-01-P-Π-O6-013



\*Размеры для справок

| Размеры, мм |      |     |      |     |      |
|-------------|------|-----|------|-----|------|
| a           | b    | d*  | e*   | f*  | g*   |
| 6,6         | 15,5 | 1,7 | 5,5  | 2,4 | 3,8  |
|             | 16,1 | 2,7 | 9,5  | 3,2 | 3,9  |
|             |      |     |      | 3,6 | 4,55 |
| 7,1         | 19,8 | 4,6 | 12,7 | 5,3 | 6,5  |
|             |      | 4,3 |      | 5,6 | 6,35 |

CP-50-1-01-P-Π-Πр-014  
 CP-50-1-01-P-Π-Πр-015



\*Размеры для справок